

Fig. 1



GBLON, SPIVAK, ET AL DOCKET #: 205114US2 INV: Masumi YOSHINO, et al SHEET 2 OF 11

Fig. 2









Fig. 3











Fig. 5








Fig. 6



Ţ

BLON, SPIVAK, ET AL DOCKET #: 205114US2 INV: Masumi YOSHINO, et al SHEET 7_OF_11_



ON, SPIVAK, ET AL DOCKET #: 205114US2 INV: Masumi YOSHINO, et al SHEET 8 OF 11

Solve Printer Online Support Contact E mail support when problem is not eliminated by any proposed workarounds. Problem is eliminated? E Mail Support Address

Solve Printer Online Support Confirm that paper is specified size. Power off and pull out paper slowly. Contact E mail support when problem is not eliminated by any proposed workarounds. Try following workarounds: E Mail Support -ile Edit View Favorites Help http://*** Address

Fig. 10




Fig. 11

